


REVISION										
REV.	DATE	DESCRIPTION	DRAWN BY							



Motor's phase	2					
Step angle	1.8°					
Rated current/phase	1.0 A(RMS)					
Resistance/phase	2.1Ω±10%					
Inductance/phase	1.5mH±20%					
Linear travel per step						
Lead screw diameter						
Lead screw lead						
Nut material						
Insulation class	В					
Insulation resistance	100MΩ(500VDC)					
Heat rise	80°C					
Motor weight	0.12 kg					
Stroke	25.4mm					
-						

Notes, 1.To maximize output force and life of linear actuators, radial load on lead screws should be avoided or be kept at a minimum.

CUSTOMER WIRING CHART	EXCITING SEQUENCE					NOTICE TO PERSONS RECEIVING THIS DRAWING THIS DRAWING IS ONLY CONDITIONALLY ISSUED, AND FOR THE SOLE PURPOSE OF INFORMING LICENSEES AND ASSOCIATE CONTRACTORS OF DINGS' MOTION, AND VENDORS THERETO AND CUSTOMERS THEREOF, RECEIPT OR POCESSION THEREOF DOES NOT CONFER TO TRANSFER ANY RIGHT IN THE SUBJECT MATTER OF THE DRAWING. THE DESIGN, CONSTRUCTION, TECHNICAL INFORMATION AND ALL OTHER SUBJECT MATTER SHOWN IN THIS DRAWING ARE AND REMAIN, EXCEPT AS MAY BE OTHERWISE INDICATED BY WRITTEN NOTICE HEREON, THE EXCLUSIVE PROPERTY OF SAID CORPORATION. THIS DRAWING MAY BE REPRODUCED ONLY BY LICENSEES AND ASSOCIATE CONTRACTORS OF SAID CORPORATION AND ONLY FOR LICENSED MANUFACTURE, AND BY VENDORS MANUFACTURING FOR SAID CORPORATION AND ONLY FOR LICENSEES AND ASSOCIATE CONTRACTORS.												
A+ —	CW	$\longrightarrow$				UNLESS OTHERWISE SPECIFIED ALL DIMENSIONS ARE IN MILLIMETERS AND TOLERANCES ARE AS BELOW PER ISO2768-ck.			DRAWN		DATE					T	CC "	
	RED A+	+		-		LIN	LINEAR ANGULAR			APPRVD		DATE	DATE		DIMG2			
	Red/wht A			+		0~3	±0.2	0~10	±15′									
	Green B+		+		_	3~6	±0.5	10~50	±30′		11K2110-100SMSN		SIZE	A3	SHEET	1/1		
	Grn/wht B-		_		+					P/N							{{}( <del>-</del> ⊕)	
+ +	CCW	,		6~30	±0.8	50 ~ 120	±1°	,				SCALE 1:1	REV.	00				
<u> </u>			$\leftarrow$			30 ~ 120	±1.5	120 ~ 400	±1.5°					JOJ (LL   1 . 1	IXEV.	00	i '	